Durno, Mark

From: Sent:

Wednesday, August 16, 2017 10:49 AM

To: Subject:

Durno, Mark Re: Test Results

Not 100% sure - will find out and get back to you.

Best Regards,



On Aug 16, 2017, at 10:07 AM, Durno, Mark < durno.mark@epa.gov > wrote:

Thanks e has a galvanized service line, correct?

Mark Durno

Homeland Security Advisor Emergency Response Branch U.S. Environmental Protection Agency 25063 Center Ridge Road Westlake, OH 44145 440-250-1743

From:



Sent: Wednesday, August 16, 2017 9:33 AM

To: George Krisztian < krisztiang@michigan.gov >; Durno, Mark < durno.mark@epa.gov >

Subject: FW: Test Results



Subject: Test Results



Attached are your recent testing results as completed by (Plumbers' Union).

A summary is as follows:

- 1. Shower: Non-detect for lead. Note this location is outside of any current regulatory requirements.
- 2. Kitchen Sink: 51 ppb for lead.
- 3. UA370 Sink (as a control): Non-detect for lead.
- 4. Meter: 100 ppb for lead. Note this location is outside of any current regulatory requirements.

5. Water Heater: 210 ppb for lead. Note this location is outside of any current regulatory requirements.

Best Regards,

